




AUTOMATED **BIN** MEASUREMENT SYSTEMS


- **Accurate**
- **Low Cost**
- **Low Power Consumption**
- **Bright LED Display**
- **Hi-Lo Alarms**
- **Works With Most Dry Material Systems**
- **Works In a wide variety of Bin Sizes.**



Rest easy with the knowledge of what's in store. Incomplete batches, lost time or production are a thing of the past with quality bin measurement systems. Automatic Bin Measurement Systems products are reasonably priced, quality designed and manufactured to provide years of dependable service.

Visit us at CemenTech.com

SIMPLE INSTALLATION



1. Drill a 11/16" hole in the top of the silo. Apply silicone caulk on bottom of waterproof enclosure and fasten enclosure to top of silo with screws.
2. Drop probe wire down through the hole.
3. Make connections to electronics module, probe wire, and customer supplied 18 AWG 3 wire cable.
4. Run cable to location of display panel. (110 Volt outlet required at this location)
5. Connect display panel to cable and calibrate.

AUTOMATED **BIN** MEASUREMENT SYSTEMS

cemen tech INC.
QUALITY WORTH TALKING ABOUT

CemenTech.com